



Simpson® Model PS61264 Gas Pressure Washer Recall

What is the problem?

Due to a manufacturing defect, the lithium battery in the pressure washer's electric start system can overheat, posing a burn hazard. While no injuries have been reported, we have received two reports of batteries overheating and damaging the units.

What should consumers do?

Consumers should immediately stop using their Simpson Model PS61264 Gas Pressure Washer and contact the manufacturer FNA® Group for instructions on how to have their unit repaired free of charge at an authorized repair facility. The repair will replace the lithium battery in the electric start system with a sealed lead acid battery. FNA Group can be contacted toll-free at 866-733-8468 from 11 a.m. to 6 p.m. ET Monday through Friday or by email at voluntaryrecall@simpsoncleaning.com.

Affected Units

This recall applies to all Simpson Model PS61264 Gas Pressure Washers. These units were sold exclusively by Lowes. **Simpson model numbers can be found on a silver label on the frame of the unit.**

Simpson PS61264 Photos

